

Charging Zi10 Battery

Fully charged battery will last approx. 1 $\frac{1}{2}$ hour or a little less. Change to 2nd battery if/when necessary! Plan ahead: Each battery will take several hours to charge (can even charge overnight).

Connect charger to camera > Plug charger into outlet > While the camera is charging the light around the record button flashes. Once charging is complete the light stops flashing.

Best to charge directly to electrical outlet, not with USB to computer.

